

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES



Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**





First Prototype

(Pictures - 11 pages)




First Prototype



Collapsible Stand





Collapsible Stand





Slide Partition




Collapsible Stand




Slide Portion w/ Sliding
Inner Frame



Stand & Slide Portion Together





①





②

Slide Portion:



- ① Sliding Inner Frame with Articulating Ramp & Wedge Cams.
- ② Sliding Inner Frame & Control Handle



This picture shows different positions of the articulating ramp and placement of beverage cases after sliding down and onto hand truck.



①- Picture of beverage cases on hand truck after first successful test.



② & ③ more pictures of beverage cases
on hand truck after first successful
test.